


Edge preparation of various thickness of metals (GMAW)

Objectives: At the end of this lesson you shall be able to

- state the edge preparation of GMAW
- describe the various types of welding process for required preparation.

Base metal preparation: For GMAW/CO₂ welding the edges and the plate surfaces for welding of ferrous and non-ferrous metals are cleaned similar to Shielded Metal Arc Welding process. The groove angle for single V butt joint in case of CO₂ welding is 40° to 45° only when compared to 60° used for shielded metal arc welding (Figs 1,2 & 3). The edge preparation required for the various types of welding process.

Fig 1



WLN227811

Fig 2

MATERIAL THICKNESS	PROCESS				
	MANUAL METALLIC ARC	MANUAL CO ₂ DIP. TRANSFER	MANUAL CO ₂ SPRAY TRANSFER	MACHINISED CO ₂	SUBMERGED ARC
0.9					
1.6					
3					
5					
6					
10					
12.5					

WLNZ27812

Fig 3

MATERIAL THICKNESS	PROCESS				
	MANUAL METAL ARC	MANUAL CO ₂ DIP TRANSFER	MANUAL CO ₂ SPRAY TRANSFER	MACHINISED CO ₂	SUBMERGED ARC
19					
25					
38					
76					


WLNZ27813

GMAW defects, causes and remedies

Objective: At the end of this lesson you shall be able to

- **state the weld defect, explain the causes and remedy if the defects.**

Excessive spatter




Excessive Spatter : scattering of molten metal particles that cool to solid form near weld bead.

Possible causes	Corrective actions
Wire feed speed too high. Voltage too high. Electrode extension (stickout) too long. Workpiece dirty. Insufficient shielding gas at welding arc. Dirty welding wire.	Select lower wire feed speed. Select lower voltage range. Use shorter electrode extension (stickout). Remove all grease, oil, moisture, rust, paint, undercoating, and dirt from work surface before welding. Increase flow of shielding gas at regulator/flowmeter and/or prevent drafts near welding arc. Use clean, dry welding wire. Eliminate pickup of oil or lubricant on welding wire from feeder or liner.

Porosity

Fig 2




VVLN227912

Porosity — small cavities or holes resulting from gas pockets in weld metal.

Possible causes	Corrective actions
Inadequate shielding gas coverage.	Check for proper gas flow rate. Remove spatter from gun nozzle. Check gas hoses for leaks. Eliminate drafts near welding arc.
Wrong gas.	Hold gun near bead at end of weld until molten metal solidifies. Use welding grade shielding gas; change to different gas.
Dirty welding wire.	Use clean, dry welding wire.
Workpiece dirty.	Eliminate pick up of oil or lubricant on welding wire from feeder or liner. Remove all grease, oil, moisture, rust, paint, coatings, and dirt from work surface before welding.
Welding wire extends too far out of nozzle.	Use a more highly deoxidizing welding wire. Be sure welding wire extends not more than (13 mm) beyond nozzle.

Incomplete fusion

Fig 3




VVLN227913


Incomplete Fusion — failure of weld metal to fuse completely with base metal or a preceeding weld bead.

Possible causes	Corrective actions
Workpiece dirty.	Remove all grease, oil, moisture, rust, paint, coatings, and dirt from work surface before welding.
Insufficient heat input.	Select higher voltage range and/or adjust wire feed speed.
Improper welding technique.	Place stringer bead in proper location(s) at joint during welding. Adjust work angle or widen groove to access bottom during welding. Momentarily hold arc on groove side walls when using weaving technique. Keep arc on leading edge of weld puddle. Use correct gun angle of 0 to 15 degrees.


Excessive penetration

<p>Fig 4</p> 		<p>Excessive Penetration — weld metal melting through base metal and hanging underneath weld.</p>
Possible causes	Corrective actions	
Excessive heat input.	<p>Select lower voltage range and reduce wire feed speed.</p> <p>Increase travel speed.</p>	

Lack of penetration


<p>Fig 5</p> 		<p>Lack of Penetration — shallow fusion between weld metal and base metal.</p>
Possible causes	Corrective actions	
Improper joint preparation.	<p>Material too thick. Joint preparation and design must provide access to bottom of groove while maintaining proper welding wire extension and arc characteristics.</p>	
Improper weld technique.	<p>Maintain normal gun angle of 0 to 15 degrees to achieve maximum penetration.</p> <p>Keep arc on leading edge of weld puddle.</p> <p>Be sure welding wire extends not more than (13 mm) beyond nozzle.</p>	
Insufficient heat input.	<p>Select higher wire feed speed and/or select higher voltage range.</p> <p>Reduce travel speed.</p>	

Burn through

<p>Fig 6</p> 		<p>Burn-Through — weld metal melting completely through base metal resulting in holes where no metal remains.</p>
Possible causes	Corrective actions	
Excessive heat input.	<p>Select lower voltage range and reduce wire feed speed.</p> <p>Increase and/or maintain steady travel speed.</p>	

Waviness of bead

Fig 7



WVLN2279/17

Waviness of Bead — weld metal that is not parallel and does not cover joint formed by base metal.

Possible causes


Unsteady hand.

Corrective actions

Support hand on solid surface or use two hands.

Distortion

Fig 1



BASE METAL
MOVES IN
THE DIRECTION
OF THE WELD BEAD

WVL28102.1

Distortion — contraction of weld metal during welding that forces base metal to move.

Possible causes

Excessive heat input.

Corrective actions

- Use restraint (clamp) to hold base metal in position.
- Make tack welds along joint before starting welding operation.
- Select lower voltage range and/or reduce wire feed speed.
- Increase travel speed.
- Weld in small segments and allow cooling between welds.