

Welder - Week 35

| S.No. | Week No. | Name of topic | No. of Hours |
|-------|----------|---|--------------|
| 1 | 35 | Edge preparation and fit up. | 7 |
| 2 | | GTAW parameters for welding of different thickness of metals | |
| 3 | | Pulsed TIG welding - brief description, pulse parameters slope up and slope down. | |