

### Turner Week-4

S. No.	Week No.	Name of Topic	No. of Hours
1	27	Different methods of forming threads.	(07 hrs.)
2		Calculation involved in finding core dia., gear train (simple gearing) calculation.	
3		Calculations involving driver-driven, lead screw pitch and thread to be cut.	