

### Turner, Week- 7

S. No.	Week No.	Name of Topic	No. of Hours
1	7	Surface plate its necessity and use. Tap - different types (Taper 2nd and bottoming) care while tapping.	(07 hrs.)
2		Dies different types and uses.	
3		Calculation involved to find Out drill size (Metric and Inch).	