

## Fitter - Week 19

S.No.	Week No.	Name of topic	No. of Hours
1	19	Setting up parameters for ARC welding machines- selection of Welding electrodes.	7
2		Care to be taken in keeping electrode.	