

Welder - Week 12

S.No.	Week No.	Name of topic	No. of Hours
1	12	Arc blow – causes and methods of controlling	6
2		Distortion in arc & gas welding and methods employed to minimize distortion	
3		Arc Welding defects, causes and Remedies	