

Electrician, Week- 40

S.No.	Week No.	Number of Topic	No. of Hours
1	40	Method of connecting three single phase transformers for three phase operation.	7 Hrs.
2		Types of Cooling, protective devices, bushings and termination etc.	
3		Testing of transformer oil.	
5		Materials used for winding and winding wires in small transformer.	