

Fitter - Week 28

S.No.	Week No.	Name of topic	No. of Hours
1	28	Method of expressing tolerance as per BIS Fits:	7
2		Definition, types, description of each with sketch.	
3		Vernier height gauge: material construction, parts, graduations (English & Metric) uses, care and maintenance.	